Approved For Release 2007/11/20: CIA-RDP78B04558A001100090022-7

OUT54121

HFS _

1964 SEP 21 23 152 SPG

PARS

ACT

Grace (File)

P 212114Z
FM NPIC WASHDC
TO RUCSBR/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEAHQ/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 2953.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

- 1. CAMERA B 15 WAS USED IN MISSION 3947 FLOWN ON 18 SEPTEMBER
 1964: PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.
 - 2. ORIGINAL NEGATIVE:
- A. THE EXPOSURE WAS OPTIMUM AND THE RESOLUTION WAS GOOD EXCEPT WHERE DEGRADED BY ATMOSPHERICS AND IMAGE SMEARING CAUSED BY VEHICLE ATTITUDE.
- B. 9R SIDE: INTERMITTENT STATIC IS PRESENT ALONG THE OUTBOARD EDGE OF THE FILM IN PARTS 1 AND 2. NUMEROUS PINHOLES WERE NOTED IN THE FIRST HALF OF THE MISSION AND THEREAFTER PINHOLES OCCUR WITH DECREASING FREQUENCY. A WANDERING PLUS DENSITY STREAK IS PRESENT INTERMITTENTLY NEAR THE INBOARD EDGE THROUGHOUT THE MISSION.

 FOREIGN MATTER (LINT) WAS FOUND ON SEVERAL FRAMES IN THE MISSION.

 PART 8 IS REELED WITH THE TAIL END ON THE OUTSIDE. A CREASE EXISTS ALONG THE OUTBOARD MARGIN OF FRAMES 2190 AND 2195. FOGGING OCCURRED IN FRAMES 2218 AND 2219. HANDLING MARKS ARE PRESENT AROUND

A.

ALL HEAT SPLICES. A HEAT SPLICE EXISTS IN FRAME 1117. A MANUFACTURING SPLICE WITH ASSOCIATED STATIC, KINKS, AND PLUS DENSITY STREAKS IS IN FRAME 492.

- C. 9L SIDE: THE MAJOR DETERENT TO THIS SIDE OF THE MISSION IS A PLUS DENSITY STREAK THAT APPEARS ALONG THE LONGITUDINAL AXIS OF THE MATERIAL. IT IS APPROXIMATELY Ø.1" WIDE AND APPEARS RANDOMLY THROUGHOUT THE MISSION. IT APPEARS ALONG THE OUTBOARD EDGE OF THE FORMAT IN FRAMES 49Ø AND 491 AND REAPPEARS ALONG THE INBOARD EDGE IN FRAMES 532 AND 1064. IT IS DETECTABLE AGAIN IN FRAMES 1749 TO 222Ø. THE FIRST 33 FRAMES CONTAIN A PROFUSION OF PINHOLES. FRAME 1034 AND 1049 CONTAIN AN EMULSION LIFT. THERE IS A MANUFACTURING SPLICE IN FRAME 1047 AND A HEAT SPLICE IN FRAME 1075.
- D. BOTH SIDES: SMEARING OF THE IMAGE DUE TO VEHICLE MOTION DURING EXPOSURE IS PREVALENT IN THIS MISSION. EXAMPLES THAT ARE TYPICAL MAY BE SEEN IN FRAMES 222, 474, 579, 2136, AND 2148. THERE ARE 2220 TITLED FRAMES IN THE MISSION.
- E. THERE ARE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS IN THE MISSION.
 - 3. POSITIVE:
- A. PI SUITABILITY IS GOOD EXCEPT WHERE DEGRADED BY ATMOSPHERICS AND WHERE IMAGERY IS SMEARED DURING VEHICLE MANEUVERS.
 - B. THE PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE APPROXIMATELY 40 PERCENT OF THE MISSION.
 SECRET

/END OF MESSAGE/